

<- Back

Forward ->

Document ID# 1212710
2002 Chevrolet Blazer - 4WD

Print

Engine Runs Rough, Service Engine Soon Light On, DTC P0300 or P0335 Set (Shim Crankshaft Sensor) #02-06-04-059 - (Dec 16, 2002)

Engine Runs Rough, Service Engine Soon Light On, DTC's P0300 or P0335 Set (Shim Crankshaft Sensor)

2002-03 Chevrolet Astro, Blazer, Express, Silverado and S-10 Truck Models

2002-03 GMC Jimmy, Safari, Savana, Sierra and Sonoma Truck Models

with 4.3L V-6 Engine (VINs W, X - RPOs L35, LU3)

Condition

Some owners may comment on a rough running condition or a Service Engine Soon (SES) light being illuminated. Upon investigation, the technician may find a DTC code P0300 or P0335.

Cause

The crankshaft sensor may be contacting the reluctor wheel.

Correction

Remove the crankshaft sensor. Refer to the Crankshaft Position Sensor Replacement procedure in the Engine Controls-4.3L sub-section of the Service Manual. After removing the sensor, inspect the end of it for witness marks that would indicate contact with the crankshaft. If contact with the reluctor ring is indicated, then inspect the front cover for cracking or other signs of alignment concerns. If the inspection indicates that the cover is causing mis-alignments, replace the cover. If replacing the cover, then the 0.5mm shim is not needed.

If the inspection of the front cover indicates that the cover is not the cause of mis-alignments, then the sensor should be shimmed. Add one shim between the sensor and the front cover. If the concern still exists, then add the second shim. Unless the sensor has been rubbed through the casing or deformed by contact with the crankshaft, it should not be replaced.

In either case, the crankshaft relearn procedure should be performed after any repairs.

Parts Information

Part Number	Description	Qty

12565102	Shim, 0.5mm thick	1-2
12562910	Sensor Crankshaft Position	as req'd

Parts are currently available from GMSPO.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
J4355	Sensor, Crankshaft Position Replace	
	C/K Truck, M Van	0.2 hr
	S/T Truck	0.3 hr
	G or L Van	0.4 hr

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION

© Copyright General Motors Corporation. All Rights Reserved.

<- Back

Forward ->

Document ID# 1212710
2002 Chevrolet Blazer - 4WD

Print