























Service and Parts Operations


[2002 Chevrolet Blazer - 4WD - Bulletins - Information](#)

Select a document to view:

-  [#00-08-48-005A Info - Distortion in Outer Surface of Vehicle Glass - \(Sep 3, 2004\)](#)
-  [#04-06-04-051A Info -Maintenance Cleaning of Fuel Injectors - \(Sep 3, 2004\)](#)
-  [#04-07-30-037 Info - Release of DEXRON III \(H-Revision\) Automatic Transmission Fluid \(ATF\) - \(Sep 3, 2004\)](#)
-  [#01-00-89-011B New Technical Assistance Information Form - \(Sep 3, 2004\)](#)
-  [#04-06-04-047A Info - Top Tier Detergent Gasoline \(Deposits, Fuel Economy, No Start, Power, Performance, Stall Concerns\) - \(Aug 31, 2004\)](#)
-  [#02-07-30-052C Info - Automatic Transmission Oil Cooler Flush and Flow Test Essential Tool J-45096 TransFlow - \(Aug 31, 2004\)](#)
-  [#02-00-89-002C Information for Dealers on How to Submit a Field Product Report - \(Aug 19, 2004\)](#)
-  [#03-00-91-001B Info - Vibration Analysis Worksheet - \(Aug 9, 2004\)](#)
-  [#01-07-30-010A Info - Torque Converter Replacement - \(Aug 6, 2004\)](#)
-  [#02-05-26-001B Info - Rear Parking Brake Shoe Retaining Spring Clip Service Kit for Drum-In-Hat \(DIH\) Equipped Vehicles - \(Aug 2, 2004\)](#)
-  [#04-08-98-002 Info - Repair Procedure for Service Sheet Metal, Craters in ELPO Surface - \(Aug 2, 2004\)](#)
-  [#03-07-30-002B Transmission Cooling System Service Tool J 45096 - Transflow Information - \(Jul 28, 2004\)](#)
-  [#02-06-03-008A Info - Low Voltage Display on IP Gauge, Lights Dim at Stop Lights, Battery Discharged, No Start, Slow Cranking, Dim Lights at Idle, Low Generator Output - \(Jul 28, 2004\)](#)
-  [#01-08-51-003A Info - Application of Anti-Corrosion Materials - \(Jul 23, 2004\)](#)
-  [#00-00-89-027B Info - Eliminating Unwanted Odors in Vehicles - \(Jul 21, 2004\)](#)
-  [#01-01-38-006C Info - Contaminated R-134a A/C Systems - Air Conditioning System Flushing Procedures and Guidelines - \(Jul 2, 2004\)](#)
-  [#02-06-03-010A Info - Battery Parasitic Drain - \(Jul 2, 2004\)](#)
-  [#99-01-38-006B Info - J-43600 ACR 2000 Essential Refrigerant Recovery/Recharge Equipment - \(Jun 22, 2004\)](#)
-  [#02-07-30-024A Info - Diagnosis of Cracked or Broken Transmission Case - \(Jun 22, 2004\)](#)
-  [#03-00-89-002A Info - New Owner Orientation Clinic Materials Now Available Online - \(Jun 22, 2004\)](#)
-  [#00-03-10-002C Info - Chemical Staining of Chrome Wheels - \(Jun 14, 2004\)](#)
-  [#00-06-01-026A Info - Intake Manifold Inspection/Replacement After Severe Internal Engine Damage - \(Jun 14, 2004\)](#)
-  [#02-08-44-007A Negative Impact of Dealer-Installed Cloth/Vinyl Roofs on XM Radio and/or OnStar Systems - \(Jun 14, 2004\)](#)
-  [#04-08-98-001 Info - Additional Material and Source for Metal Panel Bonding Adhesives -](#)

(May 26, 2004)

-  [#02-07-30-029E Info - Product Quality Center for Engine and Transmission Assembly and Transfer Case Replacement - \(May 26, 2004\)](#)
-  [#01-07-30-030A Diagnostic Information on Harsh 1-2 Upshift - \(May 20, 2004\)](#)
-  [#04-00-89-018 Info - Processing GM Accessories - Initial Quality Issues - \(May 12, 2004\)](#)
-  [#04-07-30-023 Info - Oil Pump Assembly Seal and Transmission Case Change - \(May 12, 2004\)](#)
-  [#04-06-01-013 Information on Serpentine Belt Wear - \(Apr 29, 2004\)](#)
-  [#04-08-43-003 Info - Replacement of Windshield Wiper Inserts - \(Apr 14, 2004\)](#)
-  [#04-07-30-018 Info - Availability of Transmission Shield to Protect Shift Cable/Manual Shaft Area from Snow and Ice Build-Up - \(Apr 2, 2004\)](#)
-  [#04-00-89-010 New Service Bulletin Appearance and Printing Information - \(Mar 26, 2004\)](#)
-  [#04-08-44-005 Utilizing Tech 2 To Retrieve Part Numbers for Radios, Compact Disc \(CD\) Changers and Instrument Panel Clusters \(IPC\) - \(Mar 24, 2004\)](#)
-  [#02-00-89-017A Info - Essential Tools That Include Consumable Parts/Electrical Terminals - \(Mar 15, 2004\)](#)
-  [#04-07-30-013 Info - Automatic Transmission Shift, Engine Driveability Concerns or Service Engine Soon \(SES\) Light On as a Result of the Installation of an Aftermarket Reusable, Excessively Oiled Air Filter - \(Mar 5, 2004\)](#)
-  [#01-07-30-036C Info - Diagnostic Tips for DTC P0756 - \(Mar 2, 2004\)](#)
-  [#04-08-50-006 Info - Minor Wrinkles/Creases, Discoloration, Cigarette Burns and Customer Induced Cuts and Stains on Front and Rear Driver and Passenger Seats with Leather, Vinyl or Cloth Seat Covers - \(Mar 1, 2004\)](#)
-  [#01-07-30-031A Info - 1-2, 2-3, 3-4, 4-5 Shift and Torque Converter Clutch \(TCC\) Characteristics During Cold Weather Operation on 4L60-E, 4L80-E or Allison Transmissions - \(Feb 25, 2004\)](#)
-  [#00-06-02-006A DEX-COOL Engine Coolant Information - \(Feb 13, 2004\)](#)
-  [#02-07-30-001A Diagnostic Information on DTC P0894 and P1870 - \(Feb 11, 2004\)](#)
-  [#04-07-30-006 Info - 4L65-E, 4L60-E, 4L60 and 200-4R Automatic Transmission Oil Pump Spring First and Second Design Identification - \(Feb 11, 2004\)](#)
-  [#04-06-03-002 Diagnostic Information for Intermittent Vehicle No Crank/Dead Battery - \(Feb 5, 2004\)](#)
-  [#03-00-89-008B Info - Corrosion Protection for Metal Panels with Dealer Installed Accessories Fastened by Drilled Holes - \(Jan 27, 2004\)](#)
-  [#01-07-30-042B Information on 2-3 Upshift or 3-2 Downshift Clunk Noise - \(Jan 16, 2004\)](#)
-  [#02-06-05-004A Info - Misfire DTCs P0300, P1380, P1381 and Catalytic Converter Damage Due to Installation of Alarm Systems - \(Jan 9, 2004\)](#)
-  [#04-08-48-001 Info - Rear Window Defogger - Broken Heating Grid Detection Method - \(Jan 9, 2004\)](#)
-  [#04-03-10-001 Info - Tire Puncture Repair Procedures For All Cars and Light Duty Trucks - \(Jan 6, 2004\)](#)
-  [#04-01-37-001 Info - HVAC Control Knob Replacement - \(Jan 6, 2004\)](#)
-  [#02-08-48-001A Info - Urethane Adhesives for Stationary Glass and Other Applications - \(Dec 2, 2003\)](#)
-  [#03-08-48-005A Info - Compass Zone Adjustment and Calibration Procedure During Pre-Delivery Inspection - \(Nov 13, 2003\)](#)
-  [#03-00-89-039 Info - Search Tips for Locating Preliminary Information \(PI\) Documents in Service Information - \(Nov 11, 2003\)](#)
-  [#02-00-89-006A Info - New Add Time for Labor Operation L2300 - Converter, Oxidation Catalytic-Replace - \(Nov 11, 2003\)](#)

-  [#03-07-30-056 Info - 4L60-E Automatic Transmission Oil Pump First and Second Design Identification - \(Nov 5, 2003\)](#)
-  [#03-07-30-007A Info - Engagement Time of Electronically Controlled Transmissions in General Motors Vehicles \(Garage Shifts, Park to Reverse, Neutral to Drive, Neutral to Reverse, Park to Drive, Delayed Engagement\) - \(Nov 4, 2003\)](#)
-  [#01-08-42-001A Info - Exterior Lamp Condensation and Replacement Guidelines - \(Nov 4, 2003\)](#)
-  [#01-01-38-013A Diagnostic Information to Consider Before Air Conditioning Compressor Replacement - \(Oct 29, 2003\)](#)
-  [#99-09-40-005A Info - Seat Belt Extender Availability - \(Oct 22, 2003\)](#)
-  [#01-00-89-010A Information on Use of Diagnostic Worksheet - \(Oct 22, 2003\)](#)
-  [#03-08-98-002 Info - Squeeze Type Resistance Spot Welding/Equipment - \(Oct 21, 2003\)](#)
-  [#03-07-30-043 Information Regarding Automatic Transmission Shift Lock Control Function - \(Sep 29, 2003\)](#)
-  [#03-08-48-006 Repair Information for Reconnection of Rear Window Defroster Contact or Tab - \(Sep 29, 2003\)](#)
-  [#01-04-18-001B Info - Driveline Characteristics for All-Wheel Drive \(AWD\) and Four-Wheel Drive Systems - \(Sep 25, 2003\)](#)
-  [#03-08-46-004 Info - Proper Diagnosis of OnStar System and Information Necessary When Contacting GM Technical Assistance Center \(TAC\) Regarding OnStar Parts Restriction Program Concerns - \(Sep 11, 2003\)](#)
-  [#99-04-20-002B Info - Driveline Clunk - \(Aug 21, 2003\)](#)
-  [#03-09-41-003 Info - Proper Air Bag System Diagnosis and Service - \(Jul 29, 2003\)](#)
-  [#01-06-01-011A Information on Engine Oil Consumption Guidelines - \(Jul 22, 2003\)](#)
-  [#01-08-97-001B Info - HomeLink Transceiver/Garage Door Opener Transmitter Test Kit Available As Essential Tool - \(Jul 14, 2003\)](#)
-  [#01-01-39-003A Info - J 44551 A/C Suction Screen Kit Repair Recommendations and Procedures After Catastrophic Compressor Failures - \(Jul 14, 2003\)](#)
-  [#03-08-67-004 Info - Parts Availability for Sunroof Repairs - \(Jun 25, 2003\)](#)
-  [#03-07-30-027 Info - Most Frequently Asked Questions and Answers for J 45096 TransFlow Transmission Oil Cooling System Flushing Machine - \(Jun 25, 2003\)](#)
-  [#99-07-30-022A Info - Shift Stabilization and Tow/haul Mode Feature for Hydra-Matic 4L60-E/4L65-E and 4L80-E/4L85-E Transmissions - \(Jun 5, 2003\)](#)
-  [#99-08-52-005A Info - Remote Keyless Entry Operational Characteristics - \(May 15, 2003\)](#)
-  [#03-00-89-010 Info - Bulletins Released Week of April 14, 2003 and Car and Truck Fix It Right the First Time Issues - \(Apr 24, 2003\)](#)
-  [#03-07-29-004 Info - Manual Transmission Operating Characteristics - \(Apr 14, 2003\)](#)
-  [#02-08-42-001A Info - Chemical Damage to Exterior Polycarbonate Headlamp - \(Mar 17, 2003\)](#)
-  [#99-01-39-007B Info - Automatic Air Conditioning Control Operation - \(Mar 14, 2003\)](#)
-  [#03-00-89-005 Info - Changes to Essential and Available Tool Numbering System - \(Mar 7, 2003\)](#)
-  [#03-01-38-001 Info - A/C Refrigerant System Sealer and A/C System Leak Detection Guidelines - \(Mar 7, 2003\)](#)
-  [#03-06-01-006 Info - Powertrain Quality Center for Performance Parts Engine Replacements - \(Feb 27, 2003\)](#)
- [#99-07-30-017A Info - Automatic Transmission Oil Cooler Flushing and Flow Check Procedures - \(Jan 29, 2003\)](#)
- [#03-06-04-012 Info - Inspection of All Related Wiring Harness Connections When Diagnosing Miscellaneous DTCs, Intermittent Driveability Concerns, Hard Start, No Start, Incorrect](#)

- [Gauges, Inoperative Air Conditioning - \(Jan 23, 2003\)](#)
-  [#03-08-46-001 Information Required by Technical Assistance Center from Dealers Calling with OnStar and/or XM Radio Concerns - \(Jan 23, 2003\)](#)
-  [#99-08-64-016A Info - Use of Silicone for Weatherstrip Maintenance - \(Jan 21, 2003\)](#)
-  [#00-06-01-023B Info - Engine/Balance Shaft Rattle Noise - \(Nov 26, 2002\)](#)
-  [#02-06-03-011 Electrical System Diagnostic Work Sheet, No Start, No Crank, Battery, Batteries, Generator, Gages, SES, SIR, Brake, Security, Theft, ABS, Hot DIC Messages, Lamp, Light, Battery/Generator Diag. Testing - \(Oct 30, 2002\)](#)
-  [#02-06-03-012 Proper Diagnostic Procedures for No Start, No Crank, Battery, Batteries, Generator, Gauges, SES, SIR, Brake, Security, Theft, ABS, Hot, DIC Messages, Lamp, Light, Battery and Generator Diag. Testing - \(Oct 25, 2002\)](#)
-  [#02-08-46-013 Info - OnStar Proactive Parts Shipment Process - \(Oct 15, 2002\)](#)
-  [#99-07-30-016B Diagnostic Information for Intermittent Transmission Downshift, Slip, Busy/Cycling TCC or Noisy Cooling Fan - \(Oct 14, 2002\)](#)
-  [#02-06-03-009A Info - Battery Charging Tips - \(Oct 14, 2002\)](#)
-  [#02-04-21-007 Info - Release of New Tool J 45380 - Rear Output Shaft Bushing Remover and Installer - \(Sep 11, 2002\)](#)
-  [#02-06-01-028 Info - Engine Crankcase Flush - \(Aug 9, 2002\)](#)
-  [#02-08-98-001A Info - Metal Panel Bonding - \(Jul 30, 2002\)](#)
-  [#02-00-89-008 Info - Preliminary Information \(PI\) Text Available in Service Information \(SI\) - \(Jul 19, 2002\)](#)
-  [#02-08-98-003 Info - Expandable Acoustic Foam \(Two Component Sound Dampener\) Usage with Collision Damage Repairs - \(Jun 21, 2002\)](#)
-  [#02-06-01-026 Info - Engine Identification Information - \(Jun 13, 2002\)](#)
-  [#02-07-30-028 Info - Automatic Transmission Serial Number and Site Code Locations - \(Jun 13, 2002\)](#)
-  [#02-09-41-001 Info - DTCs B1001, B1271 or B1780 Set When Replacing/Reprogramming Other Modules - \(May 24, 2002\)](#)
-  [#02-08-46-007 Info - OnStar Call Center Unable to Replenish Customers Personal Calling Minutes and Other GPS Concerns - \(May 10, 2002\)](#)
-  [#02-08-98-002 Info - Hem Flange Repair - \(May 8, 2002\)](#)
-  [#02-08-46-006 Info - Incorrect OnStar Global Positioning System \(GPS\) Location Reported During OnStar Call - \(May 6, 2002\)](#)
-  [#02-08-42-004 Info - PRNDL Display Reduced Visibility for Approximately One Minute - \(Apr 18, 2002\)](#)
-  [#02-08-46-004 Info - Cellular Error Messages Received When Trying to Connect to OnStar - \(Apr 9, 2002\)](#)
-  [#99-08-51-007A Info - Refinishing Aluminum Wheels - \(Mar 7, 2002\)](#)
-  [#02-06-01-008 Information on a New Engine Preluber Tool - \(Feb 27, 2002\)](#)
-  [#99-00-89-019B Informational - Warranty Parts Center/Corporate Parts Return Program - \(Jan 22, 2002\)](#)
-  [#01-03-10-011 Info - Tire Sidewall Damage - \(Dec 18, 2001\)](#)
-  [#01-07-30-041 Info - Transmission Fluid Leak Diagnosis - \(Dec 18, 2001\)](#)
-  [#01-07-30-043 Info - Diagnostic Tips for Slipping or Missing Second, Third and/or Fourth Gear - \(Dec 17, 2001\)](#)
-  [#01-01-38-013 Info - Diagnostic Information To Consider Before Air Conditioning Compressor Replacement - \(Dec 10, 2001\)](#)
-  [#01-08-44-014 Info - Erratic or Intermittent Operation of Radio - \(Nov 15, 2001\)](#)
-  [#01-08-97-002 Info - Programming the HomeLink Transmitter - \(Nov 14, 2001\)](#)

-  [#01-06-04-044 Info - Test Guidelines for Use of Essential Tool J41413-200 Evaporative System Tester - \(Nov 14, 2001\)](#)
-  [#01-07-31-002 Info - Improved Bleeding Procedure for Hydraulic Clutch Release System - \(Nov 2, 2001\)](#)
-  [#00-04-20-001A Info - 2-Cut vs. 5-Cut Rear Axle Ring and Pinion Gearsets - \(Oct 19, 2001\)](#)
-  [#00-06-04-011A Info - Evaporative Emissions DTC P0440, P0441, P0442, P0446 - \(Oct 4, 2001\)](#)
-  [#01-07-30-029 Info - New Product Feedback Form and Process for Automatic Transmission Core Returns - \(Oct 4, 2001\)](#)
-  [#01-03-10-007 Information on Lowering Spare Tires Stored Under Vehicle - \(Sep 25, 2001\)](#)
-  [#01-08-46-004 Info - Vehicle Integration of Cellular Phones and Normal Operating Characteristics - \(Jul 30, 2001\)](#)
-  [#01-08-44-006A Info - Cleaning the Cassette Tape Player and Clearing the CLN Message from the Radio Display - \(Jun 25, 2001\)](#)
-  [#01-09-40-002 Info - Seat Belt System Replacement Guidelines for Vehicles Involved in Collisions - \(Jun 21, 2001\)](#)
-  [#01-02-32-004 Info - Guidelines for Use of Essential Tool J 44721 Power Steering System Analyzer - \(Apr 9, 2001\)](#)
-  [#01-00-89-008 Info - Current CIPS Campaign Number to Previous Divisional Campaign Number - \(Apr 6, 2001\)](#)
-  [#99-00-89-011A Info - New Key Code Information for 10-Cut Keys - \(Mar 5, 2001\)](#)
-  [#01-00-89-006 Info - February, 2001 Bulletin Summary - \(Mar 2, 2001\)](#)

[\[HOME\]](#) [\[PUBLICATIONS\]](#)
[\[NUMBER SEARCH\]](#) [\[LATEST NEWS\]](#) [\[BULLETIN SEARCH\]](#) [\[HELP\]](#)