

---

# GM 4.3L / 262

## Value Added Quality Improvements

---

### Issues / Concern:

Intake manifold coolant leaks

Cylinder wall distortion

Cracks in lifter valley

Vibration

### JASPER Solution:

- JASPER supplies Fel-Pro PermaDry intake gaskets made of a high strength aluminized carrier and rubber molded design.
- JASPER torque plate hones to simulate cylinder head installation and to assure the cylinder walls are dimensionally correct.
- JASPER magnafluxes these areas to assure no possible cracks.
- JASPER weighs connecting rods separately as "heavy" or "light" to assure accurate matching and reduce vibration issues.

**3 Year/100,000 Mile  
Nationwide  
Parts & Labor Warranty**



**Remanufactured in the U.S.A.**

Full warranty disclosure available upon request.  
Specifications subject to change without notice.

815 Wernsing Road • P.O. Box 650 • Jasper, IN 47547-0650  
(800) 827-7455 • Fax (812) 634-1820 • [www.jasperengines.com](http://www.jasperengines.com)